

FIG. 2




FIG. 4




FIG. 5





FIG. 6






FIG. 8






FIG. 9

TIMING CHART OF SCANNING X



10/32

FIG. 10






FIG. 12




FIG.







FIG. 14












FIG. 17






FIG. 1














FIG. 21








FIG. 24




FIG. 25




FIG. 26




FIG. 27




FIG. 28






FIG. 29




29/32

FIG. 30



30/32

FIG. 31



(STRESS APPLICATION CONDITION)

Vg WAVEFORM: DUTY RATIO OF COMPENSATION SIGNAL

APPLICATION TIME IS FIXED TO 1/10

NO LIGHT EMISSION

STRESS TIME 15min

(Iphoto MEASUREMENT CONDITION)
Vg=-10V
Vsd=1V
LIGHT EMISSION 1000Ix

FIG. 32




FIG. 33

